

Message

---

**From:** Aviles, Jesse [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=9FEDD63547464C589715A846AFAD05EC-AVILES, JESSE]  
**Sent:** 9/18/2019 1:47:27 PM  
**To:** Chuck Norris; **Ex. 6 Personal Privacy (PP)**  
**CC:** 'VBI-70 CAG Administrator' [vbi170cag@gmail.com]; Linger, Agatha M. - DPHE (Denver) [Agatha.Linger@denvergov.org]; Chergo, Jennifer [Chergo.Jennifer@epa.gov]  
**Subject:** List of reports

Airtech Environmental Services, 2017a. Report of the Globeville Landing Outfall (GLO) PM10 and Metals Ambient Air Study. February 13.

Airtech Environmental Services, 2017b. Report on the Globeville Landing Outfall (GLO) PM10 and Metal Ambient Air Study. February 28.

Airtech Environmental Services, 2017c. Report of the Globeville Landing Outfall (GLO) PM10 and Metals Ambient Air Study. March 22.

Airtech Environmental Services, 2017d. Report of the Globeville Landing Outfall (GLO) PM10 and Metals Ambient Air Study. April 21.

Airtech Environmental Services, 2017e. Report of the Globeville Landing Outfall (GLO) PM10 and Metals Ambient Air Study. May 26.

Airtech Environmental Services, 2017f. Report of the Globeville Landing Outfall (GLO) PM10 and Metals Ambient Air Study. July 14.

Airtech Environmental Services, 2017g. Report of the Globeville Landing Outfall (GLO) PM10 and Metals Ambient Air Study. August 21.

Airtech Environmental Services, 2017h. Report of the Globeville Landing Outfall (GLO) PM10 and Metals Ambient Air Study. September 25.

Aguirre Engineers Inc., 1995 (Revised), Subsurface Investigation and Engineering Analysis Report I-70 from Washington Street to Brighton Boulevard City and County of Denver, Colorado CDOT Project No. IM-IR(CX) 070-4(145), Prepared for Carter & Burgess, Inc., May 9.

Brown and Caldwell, 2005a. Draft Letter Report on Groundwater Samples. September 22. Brown and Caldwell, 2005b. Final Quarterly Groundwater Monitoring Report, November/Fourth Quarter 2005, City and County of Denver, Vasquez Boulevard and Interstate 70, Operable Unit 2. December 16.

Brown and Caldwell, 2006a. Quarterly Groundwater Monitoring Report, Vasquez Boulevard and Interstate 70, Operable Unit 2, Denver, Colorado. March 14.

Brown and Caldwell, 2006a. Quarterly Groundwater Monitoring Report, Vasquez Boulevard and Interstate 70, Operable Unit 2, Denver, Colorado. May 22.

Brown and Caldwell, 2010. High Street Limited Subsurface Investigation. May 28

Buckingham, Austin, 1992. Preliminary Assessment Omaha & Grant Smelter Site, Denver, Colorado. February 27.

CDPHE, 2014. Arsenic Concentrations in Soil, Risk Management Guidance for Evaluating. July.

CDPHE, 2016. Regulation No. 41 – The Basic Standards for Ground Water. 5 CCR 1002-41. December

City and County of Denver (CCoD), 2006a. VB/I-70 OU-II Sample Results for Groundwater, Sediment and Surface Water collected on 24 January 2006, Letter report. February 27.

CCoD, 2006b. VB/I-70 OU-II Sample Results for Groundwater, Sediment and Surface Water collected on 12 April 2006, Letter report. April 28.

CH2MHill, 2002. Globeville Landing Park Soil Sampling Plan & Results, Project Number 161799, prepared for CCoD Department of Environmental Health, Environmental Services Division. October.

CH2MHill, 2003. A Guide to Performing Subsurface Work in the Vicinity of the Denver Coliseum and Globeville Landing Park. May.

CH2MHill, 2004. Denver Coliseum Barn Soil Excavations and Stockpile Summary Report, Air Monitoring Results, Soil Sampling Results, and Removal Summary.

Prepared for CCoD Department of Environmental Health, Environmental Services Division. February.

CTL Thompson, 2011. Limited Phase II Environmental Site Assessment, 40th Street Outfall, South Platte River to Blake Street, Denver, Colorado. May 10.

CTL Thompson, 2013a. Supplemental Geotechnical Investigation, 40th Street Outfall, Northwest of 40th and Blake Streets to Globeville Landing Park, Rev 1, Denver, Colorado. February 21.

CTL Thompson, 2013b. Limited Phase II Environmental Site Assessment, 40th Street Outfall, Denver, Colorado. June 13.

CTL Thompson, 2016a. Supplemental Geotechnical Investigation, 40th Street Outfall, Northwest of 40th and Blake Streets to Globeville Landing Park, Denver, Colorado. February 25.

CTL Thompson, 2016b. Lead and Arsenic Soil Sample Results, Globeville Landing Park Outfall, Phase 1B, Northeast of 38th Street and Arkins Court, Denver, Colorado. October 19.

EMSI, 2009. Remedial Investigation Vasquez Boulevard/Interstate 70 Superfund Site Operable Unit 2 – On-Facility Soils, Former Omaha and Grant Smelter. December 16.

EMSI, 2015. Data Summary Report, Environmental Conditions Investigation High Street Outfall and 40th Avenue, Storm Sewer System. September 18.

EMSI, 2016a. Final Design Report Environmental Components for Globeville Landing Outfall Project. Vasquez Boulevard/Interstate 70 Site, Operable Unit #2 Removal Action. February 5.

EMSI, 2016b. Addendum 1 Data Summary Report Environmental Conditions Investigation, High Street Outfall and 40th Avenue, Storm Sewer System, Vasquez Boulevard/Interstate 70 Site, Operable Unit #2 Removal Action. March 15.

EMSI, 2016c. Addendum 1 Final Design Report, Environmental Components for Globeville Landing Outfall Project. August 15.

EMSI, 2016d. Addendum 2 Final Design Report, Environmental Components for Globeville Landing Outfall Project. November 28.

EMSI, 2018. Addendum 3 Final Design Report, Environmental Components for Globeville Landing Outfall Project. January 31.

Jesse Aviles  
Remedial Project Manager  
Environmental Protection Agency  
Mailcode: 8SEM-RB-SA  
1595 Wynkoop Street  
Denver, CO 80202-1129  
303-312-6287  
aviles.jesse@epa.gov